

Monday, 22/10/2007 2:17:12 PM Linda Lacelle **Process Sheet** Customer : CU-DAR001 Dart Helicopters Services **Drawing Name** Job Number : ARM : 35295 -/ Estimate Number : 12578 P.O. Number : D3560 UNDER REVIEW OK PUB. 07. ZI Part Number This Issue : 22/10/2007 S.O. No. : **Drawing Number** Prsht Rev. : NC Project Number First Issue : N/A : // Type : SMALL /MED FAB **Drawing Revision** : C Previous Run : 35029 Material Written By Due Date : 29/10/2007 Checked & Approved By Qty: Each Comment : Est Rev:A New Issue 07.05.24 EC est rev B ECN 987 07.10.09 EC verified by: DD Additional Product Job Number: Seq. #: Machine Or Operation: Description: 1.0 M6061T6B0500X05000 6061-T6 Bar .50" x 5.0" Comment: Qty.: 1.4648 f(s)/Unit Total: 20.5065 f(s) 6061-T6 Bar 0.50" x 5.00" Batch: 2.0 BAND SAW BAND SAW : Comment: BAND SAW Cut blanks 16.750" long 07/10/24 (EZ 3.0 HAAS1 HAAS CNC VERTICAL MACHINING #1 Comment: HAAS CNC VERTICAL MACHINING #1 1- Mill as per Folio FA693 Rev: AA & Dwg D3560 Rev: 2-C'sink 0.196" hole on manual mill as per dwg D3560 3-Deburr per dwg D3560 4.0 QC2 INSPECT PARTS AS THEY COME OFF MACHINE Comment: INSPECT PARTS AS THEY COME OFF MACHINE

moriday, 22/10/2007 2:17:12 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: ARM Job Number: 35295 Part Number: D3560041 Job Number: Seq. #: Machine Or Operation: Description: 5.0 QC8 SECOND CHECK Comment: SECOND CHECK 6.0 D35921 PLATE Comment: Qty.: 1.0000 Each(s)/Unit Total: 14.0000 Each(s) PLATE 7.0 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 1-Weld assembly as per dwg D3560 STEP: 1- clean material (buff bracket and bottom of arm with blue pad) 2- set up bracket and arm on jig 3- preheat bracket and arm with torch 4- clean before welding with brush 5- set up machine to 135 amps 6- weld across bottom and top ends ALS+ 7- reheat with torch (69 8- on one side weld from bottom to top half way 9- same for other side (half way) 10- from half way point weld the rest of the first side (ease off pedal near end) 11- same for remaining side (ease off pedal near end) 8.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 9.0 VISUAL WELDING INSPECTION Comment: VISUAL WELDING INSPECTION N-10-80



monday, 22/10/2007 2:17:12 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: ARM Job Number: 35295 Part Number: D3560041 Job Number: Seq. #: Machine Or Operation: Description: 10.0 HAND FINISHING1 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4. 11.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSION Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 12.0 D2808 Comment: Qty.: 1.0000 Each(s)/Unit Total: 14.0000 Each(s) Spacer batch: 13.0 SMALL FAB SMALL & MEDIUM FAB RESOURCE 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 1-Press bushing in D3560 arm per dwg D3562 14.0 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 15.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 16.0 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE Job Completion U 98-0721




D3560-1 ARM (-041, SHOWN) OR D3560-2 ARM (-042, OPPOSITE) 03592-1 PLATE, SEE DETAIL A -

D3560-3 ARM (-043, SHOWN) OR D3560-4 ARM (-044, OPPOSITE) D3592-1 PLATE, -SEE DETAIL A

D3560-041 ARM WELDMENT (SHOWN), D3560-042 ARM WELDMENT (OPPOSITE)

D3560-043 ARM WELDMENT (SHOWN), D3560-044 ARM WELDMENT (OPPOSITE)




GENERAL NOTES

1) WELD PER QSI 004

2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1

3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED 4) ALL DIMENSIONS ARE IN INCHES





-			h	
C 07.06.19 B 07.01.15		07.06.19	REMOVE POWDE	ER COAT
		07.01.15	REDESIGN AS WELDMENT, ADD POCKETS	
A			NEW ISSUE	THE POUNCIS
	9	9	DART	DART AEROSPACE LTD.
	#	A H	D3560	SHEET 1 OF 3
07.06,19		ARM WELDMENT	SCALE	
	A DESIGN	B A DESIGN GO CHECKED H	B 07.01.15 A 06.09.25 DESIGN PROVED APPROVED APP	B 07.01.15 REMOVE POWDE A 07.01.15 REDESIGN AS V DESIGN OF DRAWN BY DAFT DAFT DATE D


COPYRIGHT @ 2006 BY DART AEROSPACE LTD.


THIS COCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR MY PURPOSE OR COPIED OR COMMUNICATED TO MY DTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.











DART AEROSPACE LTD	Work Order:	75245
Description: Arm	Part Number:	D3560-1
Inspection Dwg: D3560 Rev: B		2000-1
Rev. B		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X Fir	st Article	Pro	ototype
-------	------------	-----	---------

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.507	+0.000/-0.001	.50(2	_		• • • • • • • • • • • • • • • • • • • •	
Ø0.196	+0.005/-0.001	197	/			
Ø1.000	+0.010/-0.001	1.006	-			
0.500	+/-0.010	1497				
0.250	+/-0.010	. 251				
0.275	+/-0.010	.775				
0.188	+/-0.010	183				
2.000	+/-0.010	7.000		*		
1.700	+/-0.010	1.700				*
Ø0.385 x 100°	+/-0.010 x 0.5°	· 38cine				
0.250 Deep	+/-0.010	. 25.7				

Measured by:	W - WOOD SHOP			
	Audited by:	Prototype Approval:	N/A	
Date: 07-10. 79	Date: 07/10/29	Date:		
	1011017	Date:	N/A	

Rev	Date	Change		
A	07.01.17	1	Revised by	Approved
В	07.06.13	New Issue P/O D3560-041 Dimensions updated per Dwg Rev B	KJ/JLM	
		Dimensions appeared per Dwg Rev B	KJ/JLM	

